



Z i L O G

UP009101-0606

Product Update

Errata to Z8FMC160100KIT MDS Board

99C0960-001 Rev B or earlier (Motor Control MDS Board)

The errata listed in table are found in the Z8 Encore! MC Motor Control MDS board 99C0960-001 revision B or earlier.

Table 1. 99C0960-001 Rev B or Earlier (Motor Control MDS Board)

No.	Summary	Detailed Description
1	Switching to external clock may not run at actual Crystal Frequency	On earlier shipments of the kit, the board has capacitors C4 and C5 populated. The three-pin ceramic resonator on board has internal capacitors. Capacitors C4 and C5 thus created too large a capacitive load for the oscillator. Remove capacitors C4 and C5.

This publication is subject to replacement by a later edition. To determine whether a later edition exists, or to request copies of publications, contact:

2

ZiLOG Worldwide Headquarters

532 Race Street

San Jose, CA 95126-3432

Telephone: 408.558.8500

Fax: 408.558.8300

www.ZiLOG.com

Document Disclaimer

ZiLOG is a registered trademark of ZiLOG Inc. in the United States and in other countries. All other products and/or service names mentioned herein may be trademarks of the companies with which they are associated.

©2006 by ZiLOG, Inc. All rights reserved. Information in this publication concerning the devices, applications, or technology described is intended to suggest possible uses and may be superseded. ZiLOG, INC. DOES NOT ASSUME LIABILITY FOR OR PROVIDE A REPRESENTATION OF ACCURACY OF THE INFORMATION, DEVICES, OR TECHNOLOGY DESCRIBED IN THIS DOCUMENT. ZiLOG ALSO DOES NOT ASSUME LIABILITY FOR INTELLECTUAL PROPERTY INFRINGEMENT RELATED IN ANY MANNER TO USE OF INFORMATION, DEVICES, OR TECHNOLOGY DESCRIBED HEREIN OR OTHERWISE. Except with the express written approval of ZiLOG, use of information, devices, or technology as critical components of life support systems is not authorized. No licenses are conveyed, implicitly or otherwise, by this document under any intellectual property rights.